DPM 1251

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

## MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SEC	TION I	
MANUFACTURER'S NAME		EMERGENCY TELEPHONE NO.
Goodyear Aerospace Corporation		A/C 216 - 794-2382
Goodyear Aerospace Corporation  ADDRESS (Number, Street, City, State, and ZIP Code)  1210 Massillon Road Akron, Ohio	44315	
CHEMICAL NAME AND SYNONYMS		1840-C Anti-Static Coating
CHEMICAL FAMILY	FORMUL	À

SECTIO	V II -	HAZAF	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	% Wt.	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS % Solids .	26.8		BASE METAL		
CATALYST			ALLOYS •		
VEHICLE			METALLIC COATINGS		
SOLVENTS Foluene	43.	100ppr	NFILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS *	30.2	200pj	m		
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES			%	TLV (Units)	
*30.2% by Wt. (60% Isobutyl isobutyrate (40% Isobutyl acetate					
•	(40)	% Isobu	tyl acetate		
					,

SECTION III -	PHYSICAL DATA	
231 <sup>O</sup> F	SPECIFIC GRAVITY (H2O=1)	.9513
28	PERCENT, VOLATILE BY VOLUME (%)	80.97
3.2	EVAPORATION RATE ( =1)	
	231°F 28	28 PERCENT, VOLATILE BY VOLUME (%)

SECTION IV - FIRE AND E	XPLOSION HAZARD DA	TA	
FLASH POINT (Method used) 44°F closed cup	FLAMMABLE LIMITS	1.27	Uel 7.0
EXTINGUISHING MEDIA  Water spray - carbon dioxide-dry  SPECIAL FIRE FIGHTING PROCEDURES	chemical or foam		· :
UNUSUAL FIRE AND EXPLOSION HAZARDS			

	SE	CTION	V - HEA	LTH HAZARD DATA	
100 THRESHOLD LIMIT	) ppm – ceili	ng 200	) ppm (10	0 minutes)	
				nausea-unconciousness-dermatitis from	n
long skin ex		nd upp		ratory tract irritant.	
Immediately	flush eyes w	ith ple	enty of wa	ater. Get medical attention in case of	
exposure to	high concenti	cations	. Remo	ve to fresh air.	
		SECTIO	NVI - R	EACTIVITY DATA	
STABILITY	UNSTABLE	JNSTABLE:		NS TO AVOID	
	STABLI.	X			
INCOMPATABILITY					
HAZARDOUS DECO	MPOSITION PRODUC			CONDITIONS TO AVOID	
HAZARDOUS POLYMERIZATION	MAY OCCUR		37	CONSTITIONS TO AVOID	
	WILL NOT O	CCUR	X	1	
	SECT	ION VII	- SPILL	OR LEAK PROCEDURES	
STEPS TO BE TAKE	N IN CASE MATERIA	AL IS REL	EASED OR S	PILLED	
	Ar Tillian				]
WASTE DISPOSAL N	TE THOU				
	· · · · · · · · · · · · · · · · · · ·				
	SECTION	VIII - S	PECIAL P	ROTECTION INFORMATION	
Organic vapo	r respirator	to rem	nain belo	w TLV	
VENTILATION	Adequate to	rema		SPECIAL	
	MECHANICAL /Gen	ieral)		OTHER	
imperme	eable	<del></del>		goggles, if likelihood of splash.	
CHER PROTECTIVE	E EQUIPMENT				
	SE	CTION	IX - SPE	CIAL PRECAUTIONS	
PRICAUTIONS TO H	TAKEN IN HANDI	ING AND			
				lame. Keep container closed. Use wi	4.1
or repeated c	14.2		aumug Va	por. Do not get in eyes. Avoid prolo	nged
The Transfer of	THE THE PART OF				